

List of Figures

Figure 1-1	SRS Organization	1-3
Figure 1-2	The Savannah River Site and Surrounding Area	1-7
Figure 2-1	Integrated Safety Management System Continual Improvement Framework within the ISO 14001 Environmental Management System	2-2
Figure 2-2	GSA Fuel Consumption by Type, FY 2007 to FY 2017	2-7
Figure 2-3	SRS Performance in Meeting Fleet Management and Transportation Goals	2-8
Figure 3-1	D-Area Ash Project	3-4
Figure 3-2	Pathway for Processing and Dispositioning Radioactive Liquid Waste at SRS	3-5
Figure 4-1	Types and Typical Locations of Nonradiological Sampling	4-3
Figure 4-2	NPDES Industrial Wastewater Outfall Sampling Locations	4-5
Figure 4-3	NPDES Industrial Stormwater Outfall Sampling Locations	4-6
Figure 4-4	Nonradiological Surface Water Sampling Locations	4-8
Figure 4-5	Nonradiological Sediment Sampling Locations	4-10
Figure 4-6	Mercury in Sediment Locations	4-11
Figure 4-7	Average Mercury Concentration of Fish Species in the Savannah River Adjacent to the Savannah River Site	4-12
Figure 5-1	Types and Typical Locations of Radiological Sampling	5-3
Figure 5-2	10-Year History of SRS Annual Tritium Releases to the Air	5-8
Figure 5-3	Percent of Tritium Released to the Air for 2016 and 2017	5-9
Figure 5-4	Air Sampling Locations Surrounding SRS up to 25 Miles	5-10
Figure 5-5	Radiological Liquid Effluent Sampling Locations	5-15
Figure 5-6	10-Year History of Direct Releases of Tritium to SRS Streams	5-17
Figure 5-7	Radiological Surface Water Sampling Locations	5-18
Figure 5-8	10-Year Trend of Tritium in Pen Branch and Fourmile Branch (pCi/L)	5-20
Figure 5-9	Tritium Migration from SRS Seepage Basins and SWDF to SRS Streams	5-21
Figure 5-10	SRS Tritium Transport Summary	5-24
Figure 5-11	Offsite Drinking Water Sampling Locations	5-26
Figure 5-12	Tritium in Offsite Drinking Water and River Mile 141.5	5-27
Figure 5-13	Comparison of Cesium-137 Field Measurements to Laboratory Analysis for Deer Muscle Samples	5-31
Figure 5-14	Historical Trend of Average Cesium-137 Concentrations in Deer Tissue (1967-2017)	5-32

Figure 5-15	Gamma Overflight Survey of Creek Plantation with Maximum Cesium-137 Soil Concentrations from 2016 Annual Sampling and 2017 Comprehensive Survey	5-34
Figure 6-1	Exposure Pathways to Humans from Air and Liquid Effluents	6-4
Figure 6-2	Locations of Representative Persons (for DOE Compliance) and MEIs (for NESHAP Compliance) for the Air and Liquid Pathways.....	6-5
Figure 6-3	2007–2011 Wind Rose Plot for H Area	6-6
Figure 6-4	Savannah River Annual Average Flow Rates Measured by USGS at River Mile 118.8.....	6-8
Figure 6-5	Radionuclide Contributions to the 2017 SRS Total Liquid Pathway Dose of 0.22 mrem (0.0022 mSv)	6-11
Figure 6-6	Radionuclide Contributions to the 2017 SRS Total Air Pathway Dose of 0.027 mrem (0.00027 mSv)	6-13
Figure 6-7	10-Year History of SRS Maximum Potential All-Pathway Doses.....	6-16
Figure 7-1	Groundwater at SRS.....	7-3
Figure 7-2	How Contamination Gets to Soil and Groundwater	7-4
Figure 7-3	Groundwater Plumes at SRS	7-6
Figure 7-4	Location of Site Boundary Wells at SRS—Between A/M Areas and Jackson, South Carolina	7-8
Figure 7-5	Location of Monitoring Wells Sampled for Tritium in Burke and Screven Counties, Georgia.....	7-11
Figure 7-6	Tritium Concentration in Wells Sampled in Burke and Screven Counties, Georgia	7-12
Figure 7-7	Solvent Removed from A/M Area Groundwater Plume	7-14
Figure 8-1	Interrelationship between QA/QC Activities	8-3